
218.8 mm
152.4 mm
15.9 mm
50.5 mm
may be cut here
HX3 DRAWBARS #1.0
MOUNT ALL PARTS FROM BTM
P10
P11
P12
C1
P10
P11
P12
JP3
JP4
JP5
JP2
JP1
JP6
JP7
JP8
WWW.KEYBOARDPARTNER.DE
Mounting screw positions
BASS SECTION
Drawbar mounting drill pattern on base plate. M3 screws
NC
S
E
W
DB TOP MOUNT FROM BTM
2
1
129.5 mm
65.0 mm
70.0 mm
5.0 mm
7.35 mm
17.0 mm
17.0 mm
34.0 mm
204.0 mm
Drawbar mounting drill pattern on base plate. M3 screws