
218.8 mm
152.4 mm
15.9 mm
50.5 mm
may be cut here
Mounting screw positions
Base plate
Drawbar mounting drill pattern on base plate. M3 screws
NC
S
DB TOP MOUNT FROM BTM
E
W
2
1
PL40 FEDIe
C40
PL41 PED8
PL42 SUST
PL43 V/8 SM
PL44 FROM DB SET B
U40
U41
U42
R52
PL45 TO HX3 MK3
PL46 TO HX3 MK2 OR DB SET B OUT
129.5 mm
70.0 mm
65.0 mm
5.00 mm
5.0 mm
10.00 mm
7.35 mm
17.0 mm
204.0 mm
34.0 mm
Drawbar mounting drill pattern on base plate. M3 screws